



CLEVELAND-CLIFFS INC.

Hibbing Taconite Company
4950 County Highway 5 North, Hibbing, MN 55746
P 218.262.5950 clevelandcliffs.com

April 9, 2021

Regional Administrator
Air and Radiation Division
C/O Kathleen D'Agostino
US EPA, Region 5 (A-18J)
77 West Jackson Boulevard
Chicago, IL 60604
dagostino.kathleen@epa.gov

**Re: Hibbing Taconite Company's Quarter 1, 2021
Excess Emissions & Monitoring Performance Report
Permit Number 13700061**

Ms. D'Agostino:

Hibbing Taconite Company (HTC) is subject to the 2016 Revision to 2013 Taconite Federal Implementation Plan Establishing BART for Taconite Plants (FIP) which requires the installation of Continuous Emission Monitors (CEMS) to monitor nitrogen oxides (NO_x) and sulfur dioxide (SO₂). This submittal satisfies the requirements of 40 CFR 52.1235(e)(7).

Per 40 CFR 52.1235(c)(4)(v), HTC is to provide a report of each performance evaluation and QA/QC check within 60 days of completion. The most recent performance evaluation results were submitted to the EPA on February 15th, 2021 from the CGAs performed during February 2021. A summary of the results is enclosed in Attachment A. During the reporting period, there were no out-of-control periods from the daily calibration drift assessments.

HTC does not have a limit in effect at this time associated with the NO_x CEMS, therefore the proposed NO_x limit listed in the FIP is not yet enforceable. The initial SO₂ limit came into effect during the 1st Quarter 2017 reporting period and was revised on April 11, 2018 to 347.4 lbs SO₂/hr. Attached is HTC's Quarterly Excess Emissions and Monitoring System Performance Report. Considering that HTC's NO_x limit is not yet enforceable, HTC's report will contain a zero (0) in the boxes related to excess emission events. Periods of downtime that occurred during this reporting quarter are listed by monitor in the attached report.

Please contact Tasha Niemi at (218) 262-6884 or tasha.niemi@arcelormittal.com if you have any questions regarding this report.

I certify, based on the information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Sincerely,

A handwritten signature in cursive script, reading "Edward LaTendresse".

Edward LaTendresse
General Manager

Cylinder Gas Audit Results

RATA's

Emission Unit (EU)	Stack Vent (SV)	EU Description	Monitor	Pollutant	Audit Date	Results (%)	Next Test Due	Pass/Fail	Comments
020	021	Furnace Line One, Stack 1	No MR	NO _x	8/10/2020	9.0	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/10/2020	4.7	3rd Quarter, 2021	Pass	Results less than 20%
	022	Furnace Line One, Stack 2	No MR	NO _x	8/10/2020	10.1	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/10/2020	9.9	3rd Quarter, 2021	Pass	Results less than 20%
	023	Furnace Line One, Stack 3	No MR	NO _x	8/10/2020	1.4	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/10/2020	5.8	3rd Quarter, 2021	Pass	Results less than 20%
	024	Furnace Line One, Stack 4	No MR	NO _x	8/10/2020	3.4	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/10/2020	6.6	3rd Quarter, 2021	Pass	Results less than 20%
021	025	Furnace Line Two, Stack 4	No MR	NO _x	8/11/2020	6.8	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/11/2020	1.6	3rd Quarter, 2021	Pass	Results less than 20%
	026	Furnace Line Two, Stack 3	No MR	NO _x	8/11/2020	1.2	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/11/2020	3.9	3rd Quarter, 2021	Pass	Results less than 20%
	027	Furnace Line Two, Stack 2	No MR	NO _x	8/11/2020	6.5	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/11/2020	5.2	3rd Quarter, 2021	Pass	Results less than 20%
	028	Furnace Line Two, Stack 1	No MR	NO _x	8/11/2020	9.3	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/11/2020	6.4	3rd Quarter, 2021	Pass	Results less than 20%
022	029	Furnace Line One, Stack 1	No MR	NO _x	8/12/2020	7.1	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/12/2020	4.6	3rd Quarter, 2021	Pass	Results less than 20%
	030	Furnace Line One, Stack 2	No MR	NO _x	8/12/2020	3.1	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/12/2020	1.0	3rd Quarter, 2021	Pass	Results less than 20%
	031	Furnace Line One, Stack 3	No MR	NO _x	8/12/2020	6.1	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/12/2020	9.9	3rd Quarter, 2021	Pass	Results less than 20%
	032	Furnace Line One, Stack 4	No MR	NO _x	8/12/2020	3.9	3rd Quarter, 2021	Pass	Results less than 20%
				SO ₂	8/12/2020	1.4	3rd Quarter, 2021	Pass	Results less than 20%

*The full RATA report has previously been submitted to the EPA. Refer to the referenced report for more information.

CGA's									
Emission Unit (EU)	Stack Vent (SV)	EU Description	Monitor	Pollutant	Audit Date	Results (L/M%)	Next Test Due	Pass/Fail	Comments
020	021	021	No MR	NO _x	2/1/2021	0.7/1.5	2nd Quarter, 2021	Pass	None
				SO ₂	2/3/2021	0.1/0.3	2nd Quarter, 2021	Pass	
	022	022	No MR	NO _x	2/1/2021	0.5/1.2	2nd Quarter, 2021	Pass	
				SO ₂	2/3/2021	0.7/0.6	2nd Quarter, 2021	Pass	
	023	023	No MR	NO _x	2/1/2021	1.3/0.7	2nd Quarter, 2021	Pass	
				SO ₂	2/3/2021	0.4/0.1	2nd Quarter, 2021	Pass	
	024	024	No MR	NO _x	2/1/2021	0.7/0.2	2nd Quarter, 2021	Pass	
				SO ₂	2/3/2021	3.0/1.0	2nd Quarter, 2021	Pass	
021	025	025	No MR	NO _x	2/4/2021	0.6/0.7	2nd Quarter, 2021	Pass	None
				SO ₂	2/2/2021	0.2/1.8	2nd Quarter, 2021	Pass	
	026	026	No MR	NO _x	2/4/2021	0.5/0.1	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	1.4/0.6	2nd Quarter, 2021	Pass	
	027	027	No MR	NO _x	2/4/2021	1.5/2.2	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	6.0/3.3	2nd Quarter, 2021	Pass	
	028	028	No MR	NO _x	2/4/2021	0.8/0.1	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	2.5/3.8	2nd Quarter, 2021	Pass	
022	029	029	No MR	NO _x	2/3/2021	1.1/0.5	2nd Quarter, 2021	Pass	None
				SO ₂	2/2/2021	1.1/1.1	2nd Quarter, 2021	Pass	
	030	030	No MR	NO _x	2/3/2021	1.0/1.2	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	0.4/0.4	2nd Quarter, 2021	Pass	
	031	031	No MR	NO _x	2/3/2021	0.5/0.1	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	0.6/3.3	2nd Quarter, 2021	Pass	
	032	032	No MR	NO _x	2/3/2021	3.2/2.5	2nd Quarter, 2021	Pass	
				SO ₂	2/2/2021	2.5/0.5	2nd Quarter, 2021	Pass	
* Alternate Specification in PPM if noted with asterisk									

CYLINDER GAS AUDIT INFORMATION						
Gas	Test Level	Analyzers	Cylinder ID Number	Date of Certification	Type of Certification	Certified Audit Value
NOX	Low	SV021-SV032	CC344763	3/5/2020	EPA Protocol	50.35
NOX	Mid	SV021-SV032	CC708738	3/27/2020	EPA Protocol	98.76
SO2	Low	SV021-SV032	CC192395	4/7/2020	EPA Protocol	12.47
SO2	Mid	SV021-SV032	EB0065575	8/9/2018	EPA Protocol	24.26

Attachment B: Excess Emissions Report

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020, EU021, EU022**

Process Unit Description: **Pellet Indurating Furnace Line No. 1, 2 & 3; straight grate indurating furnaces.**

Total Source Operating Time in Reporting Period: **See Individual Stacks**

Total Source Operating Days in Reporting Period: **See Individual Stacks**

Emission Limitation: **347.4 lbs SO2/hr (30 day rolling average)**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **See Individual Stacks**

Analyzer Manufacturer Model No.: **See Individual Stacks**

Analyzer Serial Number: **See Individual Stacks**

Date of Latest CMS Certification or Audit: **See Individual Stacks**

Description of changes in CEMS, processes, or controls since last reporting period: **See Individual Stacks**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
See Individual Stacks				

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **See Individual Stacks**

Analyzer Manufacturer Model No.: **See Individual Stacks**

Analyzer Serial Number: **See Individual Stacks**

Date of Latest CMS Certification or Audit: **See Individual Stacks**

Description of changes in CEMS, processes, or controls since last reporting period: **See Individual Stacks**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
See Individual Stacks				

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV021**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **225**
Date of Latest CMS Certification or Audit: **2/1/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV021**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **137**

Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV021**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **8398564/18118323**
Date of Latest CMS Certification or Audit: **8/10/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV022**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T200M**

Analyzer Serial Number: **226**

Date of Latest CMS Certification or Audit: **2/1/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV022**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **136**

Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV022**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHSHS**
Analyzer Serial Number: **11318687/ 11318690**
Date of Latest CMS Certification or Audit: **8/10/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV023**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **Teledyne Moniror Labs**

Analyzer Manufacturer Model No.: **T200M**

Analyzer Serial Number: **224**

Date of Latest CMS Certification or Audit: **2/1/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV023**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **134**

Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV023**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318686/ 11318679**
Date of Latest CMS Certification or Audit: **8/10/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV024**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Moniror Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **215**
Date of Latest CMS Certification or Audit: **2/1/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	3.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	3.0
3. Total CMS Downtime (%)	0.14%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
01/23/2021 23:00	01/24/2021 01:59	3.0	Monitor equipment malfunctions	Replaced failed exhaust pump. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU020 SV024**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**

Total Source Operating Days in Reporting Period: **88 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **135**

Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU020 SV024**

Process Unit Description: **Pellet Indurating Furnace Line No. 1; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,072 hours**
Total Source Operating Days in Reporting Period: **88 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **13438339/11168507**
Date of Latest CMS Certification or Audit: **8/10/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: January 1, 2021 - March 31, 2021
Company Name: Hibbing Taconite Company
Company Address: 4950 Hwy 5 North
Hibbing MN
Process Unit Identification: EU021

Process Unit Description: Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.

Total Source Operating Time in Reporting Period: 1,597 hours
Total Source Operating Days in Reporting Period: 70 days
Emission Limitation: N/A
Analyzer Analyte: NOX
Analyzer Manufacturer: See Individual Stacks
Analyzer Manufacturer Model No.: See Individual Stacks
Analyzer Serial Number: See Individual Stacks
Date of Latest CMS Certification or Audit: See Individual Stacks

Description of changes in CEMS, processes, or controls since last reporting period: See Individual Stacks

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
See Individual Stacks				
		0.0		
		0.00		
		0.00		
		0.00		
		0.00		
		0.00		
		0.00		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU021 SV025**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**

Total Source Operating Days in Reporting Period: **70 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T200M**

Analyzer Serial Number: **199**

Date of Latest CMS Certification or Audit: **2/4/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU021 SV025**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**

Total Source Operating Days in Reporting Period: **70 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **119**

Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV025**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHSH**
Analyzer Serial Number: **11318688/ 11318689**
Date of Latest CMS Certification or Audit: **8/11/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV026**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **197**
Date of Latest CMS Certification or Audit: **2/4/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU021 SV026**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**

Total Source Operating Days in Reporting Period: **70 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **116**

Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV026**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318672/ 8398565**
Date of Latest CMS Certification or Audit: **8/11/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV027**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **179**
Date of Latest CMS Certification or Audit: **2/4/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	4.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	4.0
3. Total CMS Downtime (%)	0.25%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
3/17/21 2:00	3/17/2021 5:59	4.0	Monitor equipment malfunctions	Replaced failed sample pump. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV027**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **SO2**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T100H**
Analyzer Serial Number: **115**
Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	4.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	4.0
3. Total CMS Downtime (%)	0.25%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
3/17/21 2:00	3/17/2021 5:59	4.0	Monitor equipment malfunctions	Replaced failed sample pump. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV027**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318684/ 11318691**
Date of Latest CMS Certification or Audit: **8/11/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV028**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **198**
Date of Latest CMS Certification or Audit: **2/4/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV028**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **SO2**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T100H**
Analyzer Serial Number: **117**
Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU021 SV028**

Process Unit Description: **Pellet Indurating Furnace Line No. 2; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **1,597 hours**
Total Source Operating Days in Reporting Period: **70 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318678/ 11318673**
Date of Latest CMS Certification or Audit: **8/11/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of downtime during this reporting period.				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU022**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**

Total Source Operating Days in Reporting Period: **90 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **See Individual Stacks**

Analyzer Manufacturer Model No.: **See Individual Stacks**

Analyzer Serial Number: **See Individual Stacks**

Date of Latest CMS Certification or Audit: **See Individual Stacks**

Description of changes in CEMS, processes, or controls since last reporting period: **See Individual Stacks**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
See Individual Stacks				
		0.00		
		0.00		
		0.00		
		0.00		
		0.00		
		0.00		
		0.00		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV029**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **213**
Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: January 1, 2021 - March 31, 2021
Company Name: Hibbing Taconite Company
Company Address: 4950 Hwy 5 North
Hibbing MN
Process Unit Identification: EU022 SV029
Process Unit Description: Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.
Total Source Operating Time in Reporting Period: 2,159 hours
Total Source Operating Days in Reporting Period: 90 days
Emission Limitation: N/A
Analyzer Analyte: SO2
Analyzer Manufacturer: Teledyne Monitor Labs
Analyzer Manufacturer Model No.: T100H
Analyzer Serial Number: 129
Date of Latest CMS Certification or Audit: 2/2/2021
Description of changes in CEMS, processes, or controls since last reporting period: N/A

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV029**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHSHS**
Analyzer Serial Number: **11318676/ 11318683**
Date of Latest CMS Certification or Audit: **8/12/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU022 SV030**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**

Total Source Operating Days in Reporting Period: **90 days**

Emission Limitation: **N/A**

Analyzer Analyte: **NOX**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T200M**

Analyzer Serial Number: **212**

Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU022 SV030**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**

Total Source Operating Days in Reporting Period: **90 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **130**

Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV030**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318682/ 11318681**
Date of Latest CMS Certification or Audit: **8/12/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV031**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **214**
Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	17.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	17.0
3. Total CMS Downtime (%)	0.79%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
02/05/2021 22:00	02/05/2021 22:59	1.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/06/2021 05:00	02/06/2021 07:59	3.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/06/2021 21:00	02/07/2021 08:59	12.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/14/2021 03:00	02/14/2021 03:59	1.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV031**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **SO2**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T100H**
Analyzer Serial Number: **132**
Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	17.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	17.0
3. Total CMS Downtime (%)	0.79%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
02/05/2021 22:00	02/05/2021 22:59	1.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/06/2021 05:00	02/06/2021 07:59	3.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/06/2021 21:00	02/07/2021 08:59	12.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
02/14/2021 03:00	02/14/2021 03:59	1.0	Other known causes	Extreme cold caused freeze up. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV031**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHS**
Analyzer Serial Number: **11318670/ 11318677**
Date of Latest CMS Certification or Audit: **8/12/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

**Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)**

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV032**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **NOX**
Analyzer Manufacturer: **Teledyne Monitor Labs**
Analyzer Manufacturer Model No.: **T200M**
Analyzer Serial Number: **195**
Date of Latest CMS Certification or Audit: **2/3/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**

Company Name: **Hibbing Taconite Company**

Company Address: **4950 Hwy 5 North**
Hibbing MN

Process Unit Identification: **EU022 SV032**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**

Total Source Operating Days in Reporting Period: **90 days**

Emission Limitation: **N/A**

Analyzer Analyte: **SO2**

Analyzer Manufacturer: **Teledyne Monitor Labs**

Analyzer Manufacturer Model No.: **T100H**

Analyzer Serial Number: **131**

Date of Latest CMS Certification or Audit: **2/2/2021**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	0.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	0.0
3. Total CMS Downtime (%)	0.00%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
There were no periods of monitor downtime during this reporting period				
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		

Quarterly Excess Emissions and Monitoring System Performance Report
Required by 40 CFR 52.1235(e)(7)

Reporting Period Dates: **January 1, 2021 - March 31, 2021**
Company Name: **Hibbing Taconite Company**
Company Address: **4950 Hwy 5 North**
Hibbing MN
Process Unit Identification: **EU022 SV032**

Process Unit Description: **Pellet Indurating Furnace Line No. 3; straight grate indurating furnace.**

Total Source Operating Time in Reporting Period: **2,159 hours**
Total Source Operating Days in Reporting Period: **90 days**
Emission Limitation: **N/A**
Analyzer Analyte: **Stack Flow**
Analyzer Manufacturer: **Sick Maihak**
Analyzer Manufacturer Model No.: **FLSE 100-H K178 35SHSHS**
Analyzer Serial Number: **11318680/ 11318671**
Date of Latest CMS Certification or Audit: **8/12/2020**

Description of changes in CEMS, processes, or controls since last reporting period: **N/A**

Excess Emissions Summary	
1. Duration of excess emissions in reporting period due to:	
a. Startup/Shutdown	0.0
b. Control equipment problems	0.0
c. Process problems	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total duration of excess emissions (days)	0.0
3. Total duration of excess emissions (%)	0.00%

CMS Performance Summary	
1. CMS Downtime in reporting period due to:	
a. Monitor equipment malfunctions	2.0
b. Non-Monitor equipment malfunctions	0.0
c. Quality assurance calibration	0.0
d. Other known causes	0.0
e. Unknown causes	0.0
2. Total CMS Downtime (hours)	2.0
3. Total CMS Downtime (%)	0.09%

Excess Emissions Details						
Start Date & Time	End Date & Time	Duration of Excess Emissions (hours)	Pollutant	Magnitude of Emissions	Cause of Excess Emissions	Corrective Action
There were no periods of excess emissions during this reporting period						

CMS Downtime Details				
Start Date & Time	End Date & Time	Duration of Monitor Downtime (hours)	Cause of Monitor Downtime	Corrective Action
02/16/2021 21:00	02/16/2021 21:59	1.0	Monitor equipment malfunctions	Thawed frozen flow meter. Returned to operation. Followed SSM plan.
03/24/2021 18:00	03/24/2021 18:59	1.0	Monitor equipment malfunctions	Flow meter cleaned. Returned to operation. Followed SSM plan.
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		
		0.0		